

2012

# Kits de Distribución



| Aplicacion Vehiculo (Resumen)  | Codigo Kit SKF                                     | Tensor   | Correa       | Bomba de Agua |
|--|--|--|--------------|---------------|
| VW Gacel-Gol-Pointer-Polo-Saveiro-Senda 1.6-1.8-2.0 Nafta (Todos motor Audi)   | <b>VKMA 01000 A</b>                                | VKM 11000 H                                      | 121SX180     |               |
| VW Gacel-Gol-Pointer-Polo-Saveiro-Senda 1.6-1.8-2.0 Nafta (Todos motor Audi) - Correa compuesto HSN - Recomendado para vehículos equipados con GNC   | <b>VKMA 01000 AD</b>                               | VKM 11000 H                                      | 121SX180H    |               |
| VW Gol-Saveiro-Senda 1.6 Diesel  | <b>VKMA 01010 A</b>                                | VKM 11010  | 135SHX254    |               |
| VW Golf-Passat-Polo 1.9 D/TDI/SDI  | <b>VKMA 01011 A</b>                                | VKM 11010  | 137SHX254H   |               |
| VW Gol-Polo-Saveiro 1.9 Diesel   | <b>VKMA 01013 A</b>                                | VKM 11014  | 137SHX254H   |               |
| VW Caddy-Golf-Passat-Polo 1.9 TDI/SDI  | <b>VKMA 01014 A</b>                                | VKM 11014<br>VKM 21012                           | 137SHX254H   |               |
| SEAT Cordoba / Ibiza 1.4 motor AKK<br>VW Golf 1.4 Motores AEX, APQ   | <b>VKMA 01106 A</b>                                | VKM 11106  | 135STP8M190H |               |
| VW Golf 1.4 Motores AEX, APQ - 1390 cc -Incluye Bomba de Agua-   | <b>VKMC 01106-1</b>                                | VKM 11106  | 135STP8M190H | VKPC 81215    |
| VW Fox-Gol Trend-Suran Motores 1.6 -Incluye Bomba de Agua-   | <b>VKMC 01106-2</b>                                | VKM 11106  | 135STP8M190H | VKPC 81210    |
| VW Caddy 1.4 Motores AEX, APQ - 1390 cc -Incluye Bomba de Agua-  | <b>VKMC 01107</b>                                  | VKM 11107  | 135STP8M190H | VKPC 81215    |
| SEAT Cordoba / Ibiza / Inca 1.6 motor BAH<br>VW Fox / Suran / Crossfox / Gol Trend / Voyage 1.6 motor BAH , BJA, BLH, BPA  | <b>VKMA 01107 A</b>                                | VKM 11107  | 135STP8M190H |               |
| Audi A3 1.6 Motores AEH, AKL, APF, AVU, BFQ<br>VW Golf 1.6 Motores AEH, AKL, APF, AVU  | <b>VKMA 01113</b>                                  | VKM 11113  | 138STP8M230H |               |
| VW Golf IV, Vento (Motor 2,0 APK, AQY, AZG, AZH, AZJ, BEH) Passat (Motor 2,0 AZM) Polo III (Motor 2,0 BBX) Sharan (Motor 2,0 ATM) -Incluye Bomba de Agua-  | <b>VKMC 01113-2</b>                                | VKM 11113  | 138STP8M230H | VKPC 81620    |
| Audi A3 1.9 TDI 110 Motor AHF Desde Motor N° 006 066 Hasta Motor N° 595 000 -Incluye Bomba de Agua-  | <b>VKMC 01131</b>                                  | VKM 11130<br>VKM 21004<br>VKM 21130              | 141SHX254H   |               |
| Audi A3 1.9 TDI 110 Motor AHF Desde Motor N° 006 066 Hasta Motor N° 595 000 -Incluye Bomba de Agua-  | <b>VKMC 01131</b>                                  | VKM 11130<br>VKM 21004<br>VKM 21130              | 141SHX254H   | VKPC 81623 A  |
| Audi A3 (8L1)-A4 (8D2, B5)-A4 (8E2, B6)-A6 (4B, C5) Motor 1.9 TDI -<br>VW Bora (1J2)-Golf IV (1J1)-New Beetle (9C1, 1C1)-Passat (3B2)-Sharan (7M6, 7M8, 7M9) Motor 1.9 TDI   | <b>VKMA 01142</b>                                  | VKM 11142<br>VKM 21142                           | 120SP300HT   |               |
| Audi A4/A4 Avant 2.4 2.7 RS4/S4/Turbo 2.8 Motores AGA,AGB,AMM / A6 2.8 2.7 Turbo 2.8 Motores ACK,ARE / A8 2.8 VW Passat  | <b>VKMA 01202</b>                                  | VKM 11202<br>VKM 21201                           | 5493XS       |               |
| Vw. Golf - Passat / Audi A3 - A4 - A6 - TT / Motor 2.0 FSI - TFSI  | <b>VKMA 01222</b>                                  | VKM 11222<br>VKM 21220<br>VKM 21223              | 148SP230H    |               |
| Audi A3-A4 1.9 TDI Motores ASZ, BKC<br>VW Bora-Golf 1.9 TDI Motores AXR, BKC, BRU  | <b>VKMA 01250</b>                                  | VKM 11250<br>VKM 21147                           | 120SP300HT   |               |
| Audi A3 (Motor 1,9TDI ASZ desde Motor 115001); A4 (Motor 1,9 TDI AVF, AWX desde chasis 8E-2-297101); A6 (Motor 1,9TDI AVF, AWX desde chasis 4B-2-120001); VW Vento (Motor 1,9 TDI ASZ desde chasis 1J-2-525001; 1J-2D352774); Golf IV (Motor 1,9 TDI ASZ); Passat (Motor 1,9 TDI AVF, AWX); Sharan (Motor 1,9 TDI ASZ) Seat Leon II (Motor 1,9 TDI BKC, BLS, BXE) Toledo II, III, (Motor 1,9TDI ASZ, BJB, BKC, BLS, BXE) -Incluye Bomba de Agua- | <b>VKMC 01250-1</b>                                | VKM 11250<br>VKM 21147                           | 120SP300HT   | VKPC 81626    |
| Audi A3 / Seat Cordoba - Ibiza / VW Golf - Passat - Transporter - Polo - Motor BKC, BLS, BXE 1,9 TDI -Incluye Bomba de Agua-   | <b>VKMC 01250-2</b>                                | VKM 11250<br>VKM 21147                           | 120SP300HT   | VKPC 81418    |
| Audi A3 1.9 TDI Motor ASV<br>VW Bora-Golf 1.9 TDI Motores AGR, AHF, ASV  | <b>VKMA 01251</b>                                  | VKM 11130<br>VKM 21004<br>VKM 21130<br>VKM 21131 | 141SHX250HT  |               |
| Audi A3 (8L1) 1.9 TDI 90-110 Motor ALH-AHF-ASV - Seat Cordoba (6K2) 1.9 Motor AGP-AGR-ALH-AQM.ASV.AGP (6K5) - Ibiza III- Inca- Leon I - Toledo II SDI-TDI 90/110 - Vw. Bora (1J2) -Caddy (9K9A)-STATE (9K9B) PICKUP (9U7) - Golf IV (1J1/5). -Incluye Bomba de de Agua-  | <b>VKMC 01251</b>                                  | VKM 11130<br>VKM 21004<br>VKM 21130<br>VKM 21131 | 141SHX250HT  | VKPC 81623 A  |
| Audi A3 (8P1)-A3 Sportback (8PA)-A4 (8EC)-A4 Avant (8ED)-A6 (4F2)-A6 Avant (4F5) - VW Golf V (1K1) 2.0 TDI   | <b>VKMA 01255</b>                                  | VKM 11255<br>VKM 21147<br>VKM 21256              | 141SHX300H   |               |
| Audi A3 (8P1)-A3 Sportback (8PA) - VW Golf V (1K1) Motores 2.0 TDI AZV (Desde Motor N° 1K-7-000 001 en adelante)   | <b>VKMA 01259</b>                                  | VKM 11255<br>VKM 21147<br>VKM 21259              | 141SHX300H   |               |
| VW Golf - Passat - Tiguan / Audi A3 - A4 - A5 - A6 - Q5 - TT - Motor 2,0 TDI   | <b>VKMA 01263</b>                                  | VKM 11263<br>VKM 21142<br>VKM 21147<br>VKM 21256 | 5648XS       |               |
| VW Fox 1.9 SDI - Suran 1.9 SDI - Polo 1.9 SDI  | <b>VKMA 01275</b>                                  | VKM 11130<br>VKM 21004<br>VKM 21130              | 141SHX250HT  |               |
| Audi A4 1.8 Turbo Motores ANB, ANP, APU, ARK - 1781 cc (Incluye amortiguador/accesorios)<br>VW Passat 1.8 Turbo 20V Motores AEB, ANB, APU - 1781 cc (Incluye amortiguador/accesorios)  | <b>VKMA 01908</b>                                  | VKM 11008<br>VKM 21004<br>VKM 11009              | 153X25 HSN   |               |
| Audi A4 - A6 / Vw. Passat 1.8 - 2.0  | <b>VKMA 01918</b>                                  | VKM 11018<br>VKM 11117                           | 150STP8N230H |               |
| Audi A3 1.8 Motores AGN, APG Hasta motor N° CH 8L-Y-125 000<br>VW Bora 1.8T Motores AGU, AUM Hasta motor N° CH 1j-Y-850 000  | <b>VKMA 01935<br/>(Reemplaza a<br/>VKMA 01115)</b> | VKM 11115<br>VKM 21115                           | 150STP8M230H |               |

| Aplicacion Vehículo (Resumen)   | Codigo Kit SKF | Tensor                               | Correa              | Bomba de Agua |
|---|----------------|--------------------------------------|---------------------|---------------|
| Audi A3 1.8 Motores AGN, APG - 1781 cc (Hasta motor N° CH 8L-Y-125 000 / VW Bora 1.8T Motores AGU, AUM - 1781 cc (Hasta motor N° CH 1j-Y-850 000)   | VKMA 01935     | VKM 11115<br>VKM 21115               | 150STP8M230H        |               |
| Audi A3 (Motor 1,8T AGU, AJQ, APP, AQA, ARX, ARY, ARZ, AUM, AUQ, AGN, AGP hasta chasis 8L-Y-125001); A6 (Motor 1,8 AJP, ANQ, AQE, ARH,) TT (Motor 1,8T AJQ, AMU, APP, APX, ARY, ATC, AUQ, AWP, BAM hasta chasis 8N-Y-095000)<br>VW Sharan (Motor 1,8T AJH) New Beetle (Motor 1,8T APH hasta motor 028500); Golf IV (Motor 1,8T AGU, ARZ, AUM, AUQ hasta chasis 1J-Y-850000)<br>Seat Toledo, Leon (Motor 1,8T AJQ, APP, ARY, AUQ hasta chasis 1M-YB088000, 1M-YR016500)–Incluye Bomba de Agua– | VKMC 01935     | VKM 11115<br>VKM 21151               | 150STP8M230H        | VKPC 81620    |
| Audi A3-A4-TT - Seat Cordoba, Ibiza, Leon I, Toledo II - Vw. Bora, Golf, N. Beetle, Sharan 1.8/1.8 Turbo Motores AGN, APG, BAF, AGU, AUM, BAE, ARZ, APH. Incluye Bomba de de Agua   | VKMC 01936     | VKM 11116<br>VKM 21115               | 150STP8M230H        | VKPC 81620 A  |
| Audi A4 2.5 TDI Motores BCZ, BDG, BFC (Incluye amortiguador / accesorios)<br>VW Passat 2.5 TDI Motores BAU, BDG, BDH (Incluye amortiguador / accesorios)  | VKMA 01952     | VKM 11150<br>VKM 11151<br>VKM 21151  | 87X24 HSN<br>207X30 |               |
| Kit para sist. Auxiliares Audi A3 1.8T (8L1)-TT 1.8T (83N) - TT Roadster 1.8T (8N9)<br>VW Bora 1.8T (1J2)-Golf IV 1.8T (1J1)  | VKMA 31204     | VKM 31011                            | VKMW 6DK1195        |               |
| BMW Serie 3 Motores M 20 B 20 - M 20 B 25   | VKMA 08110     | VKM 18100                            | 127 X 25            |               |
| Chrysler Neon 2.0 16V SOHC  | CRA.VKMA41002  | CRA.<br>VKM51001                     | 112SP290H           |               |
| Chrysler Neon 2.0 16V DOHC  | CRA.VKMA41004  | CRA.<br>VKM51001<br>CRA.<br>VKM51001 | 150X29              |               |
| Chrysler Stratus 2.5 V6   | CRA.VKMA95613  | CRA.<br>VKM61000<br>CRA.<br>VKM75000 | 187SHP+320H         |               |
| Citroen Jumper motor SOFIM 2800 HDi<br>Peugeot Boxer 2.8 Hdi motor SOFIM 2800 Hdi   | VKMA 02383     | VKM 22380<br>VKM 22385               | 152SHDS300H         |               |
| Peugeot Expert 1,6 Motor 222A2 (1580 SPI)   | VKMA 02410 A   | VKM 12200 H                          | 138SHPN150          |               |
| Citroën Saxo-Xsara 1.4 Motor TU3JP<br>Peugeot 106-206 1.4 Motor TU3JP   | VKMA 03110 A   | VKM 13100                            | 108SP170H           |               |
| Citroën Saxo-Xsara-ZX 1.6 Motor TU5JP<br>Peugeot 205-206-306 1.6 Motor TU5JP-TU3JP  | VKMA 03111 A   | VKM 13100                            | 101SP170H           |               |
| Citroen Saxo / Xsara 1.5 D / Peugeot 106 I y II 1.5 D / Rover 100 1.5 D ( motor TUD5)   | VKMA 03121     | VKM 13120<br>VKM 23120               | 58136x25,4 HSN      |               |
| Citroen Berlingo-C3-Xsara 1.6 16V Motor TU5JP4 (Hasta N° 1806404)<br>Peugeot 206-307-Partner 1.6 16V Motor TU5JP4 (Hasta N° 1806404)  | VKMA 03132     | VKM 13132<br>VKM 23130               | 134SP254H2          |               |
| Citroën Berlingo, C3, Xsara; Peugeot 206, 307, Partner (Motor 1,6 16V TU5JP4 hasta motor 1806404) –Incluye Bomba de Agua–   | VKMC 03132     | VKM 13132<br>VKM 23130               | 134SP254H2          | VKPC 83430    |
| Citroën C3 1.4 HDi / Ford EcoSport-Nuevo Fiesta 1.4 TDCi / Peugeot 206 1.4 Hdi –Incluye Bomba de Agua–  | VKMC 03140     | VKM 13140<br>VKM 23140               | 144SP+254H          | VKPC 83140    |
| Citroën C3 1.4 HDi<br>Peugeot 206 1.4 HDi   | VKMA 03140 A   | VKM 13140<br>VKM 23140               | 144SP+254H          |               |
| Citroën Berlingo-Xantia-Xsara 1.8 Motor XU7JB/JP<br>Peugeot 306-Partner 1.8-2.0 Motores XU7JP / XU10J2  | VKMA 03201 A   | VKM 13100                            | 114SP+170H          |               |
| Peugeot 405 1.9 16V   | VKMA 03210     | VKM 13210<br>VKM 13210               | 133SP254H           |               |
| Citroen Xsara 2.0 16V Motor XU10J4R (07-98 09-00)<br>Peugeot 306-406 2.0 16V Motor XU10J4R (03-97 05-04)  | VKMA 03213     | VKM 13202<br>VKM 23213               | 136SP+254H          |               |
| Peugeot 306 1.8 16V Motor XU7JP4 (CEE 95) OE 9637058080   | VKMA 03214     | VKM 13214<br>VKM 23214               | 136SP+254H          |               |
| Peugeot 306 1.8 16V Motor XU7JP4 (CEE 2000) OE 9635336880   | VKMA 03216     | VKM 13216<br>VKM 23214               | 136SP+254H          |               |
| Citroën C4-C5-Xsara-Xsara Picasso 2.0 16V Motor EW10J4<br>Peugeot 206-307-406-407-Expert 2.0 16V Motor EW10J4   | VKMA 03235     | VKM 13234<br>VKM 23230               | 153SP254H1          |               |
| Citroën BX-ZX 1.8 D Motor XUD<br>Peugeot 205-306 1.8 D Motor XUD7   | VKMA 03240     | VKM 13240<br>VKM 23240               | 136SP254H           |               |
| Citroën Berlingo, Xsara, Xsantia, ZX 1.7-1.8-1.9 Diesel y Turbo Diesel Motores XUD7-XUD7T-XUD9-XUD9TE / Fiat Ducato 1.9 Diesel y Turbo Diesel<br>Peugeot 205-306-405-Boxer-Partner 1.7-1.8-1.9 Diesel y Turbo Diesel Motores XUD7-XUD7T-XUD9-XUD9TE   | VKMA 03241 A   | VKM 13241<br>VKM 23241               | 136SP254H           |               |
| Citroën Berlingo, Xsara, Xsantia, ZX 1.7-1.8-1.9 Diesel y Turbo Diesel Motores XUD7-XUD7T-XUD9-XUD9TE / Fiat Ducato 1.9 Diesel y Turbo Diesel<br>Peugeot 205-306-405-Boxer-Partner 1.7-1.8-1.9 Diesel y Turbo Diesel Motores XUD7-XUD7T-XUD9-XUD9TE –Incluye Bomba de Agua–   | VKMC 03241 A   | VKM 13241<br>VKM 23241               | 136SP254H           | VKPC 83420 A  |
| Citroën Berlingo-Xsara 1.9 Diesel Motor DW8<br>Peugeot 206-306-Partner 1.9 Diesel Motor DW8   | VKMA 03244 A   | VKM 13244<br>VKM 23246               | 140SP+254H          |               |
| Citroën Berlingo-Xsara 1.9 Diesel Motor DW8<br>Peugeot 206-306-Partner 1.9 Diesel Motor DW8 –Incluye Bomba de Agua–   | VKMC 03244 A   | VKM 13244<br>VKM 23246               | 140SP+254H          | VKPC 83639 A  |
| Citroën Berlingo-Xsara-Xsara Picasso 2.0 HDi Motor DW10TD<br>Peugeot 206-306-307-406-Partner 2.0 HDi Motor DW10TD –Incluye Bomba de Agua–   | VKMC 03247     | VKM 13244<br>VKM 23246               | 141SP+254H          | VKPC 83639 A  |

| Aplicacion Vehiculo (Resumen)   | Codigo Kit SKF        | Tensor   | Correa               | Bomba de Agua |
|---|-----------------------|--|----------------------|---------------|
| Citroën Berlingo-Xsara-Xsara Picasso 2.0 HDi Motor DW10TD<br>Peugeot 206-306-307-406-Partner 2.0 HDi Motor DW10TD   | <b>VKMA 03247 A</b>   | VKM 13244<br>VKM 23246                           | 141SP+254H           |               |
| Citroën C8 (Motor 2.0 HDi DW10ATED4)<br>Peugeot 806, 807, Expert (Motor 2.0 HDi DW10ATED4)  | <b>VKMA 03248</b>     | VKM 13246<br>VKM 23246                           | 144SP254H            |               |
| Citroën Saxo 1.1 Motor TU1JP<br>Peugeot 106 1.1 Motor TU1JP –Incluye Bomba de Agua–   | <b>VKMC 03253</b>     | VKM 13253 A                                      | 100SP170H            | VKPC 83644    |
| Citroën Berlingo-C3-Saxo 1.4 8V Motor TU3A, TU3JP<br>Peugeot 106-206-Partner 1.4 8V Motor TU3A, TU3JP   | <b>VKMA 03254 A</b>   | VKM 13253  | 104SP170H1           |               |
| Citroën Berlingo-C3-Xsara 1.6 16V Motor TU5JP4 (Desde N° 1806405)<br>Peugeot 206-307-Partner 1.6 16V Motor TU5JP4 (Desde N° 1806405)  | <b>VKMA 03256</b>     | VKM 13256<br>VKM 23256                           | 134SP254H2           |               |
| Citroën Berlingo-C3-C4-Xsara -Xsara Picasso1.6 16V Motor TU5JP4 - 1587 cc (Desde N° 1806405)<br>Peugeot 206-207-307-Partner 1.6 16V Motor TU5JP4 - 1587 cc (Desde N° 1806405) –Incluye Bomba de Agua– | <b>VKMC 03256</b>     | VKM 13256<br>VKM 23256                           | 134SP254H2           | VKPC 83430    |
| Citroën C4-C4 Picasso-C5 II-C8 2.0 Hdi Motor DW10BTED4<br>Peugeot 307-407-807-Expert II 2.0 Hdi Motor DW10BTED4   | <b>VKMA 03257</b>     | VKM 13257<br>VKM 23257                           | 116SP+254H           |               |
| Citroën C4-C4 Picasso-C5 II-C8 2.0 Hdi Motor DW10BTED4<br>Peugeot 307-407-807-Expert II 2.0 Hdi Motor DW10BTED4 –Incluye Bomba de Agua–   | <b>VKMC 03257</b>     | VKM 13257<br>VKM 23257                           | 116SP+254H           | VKPC 83643    |
| Peugeot 206 - 207 - 308 - 3008 - 407 - Partner<br>Citroën Berlingo - C4-C5 Motor HDi DV6TED4  | <b>VKMA 03259</b>     | VKM 13140<br>VKM 23140                           | 137X25HSN            |               |
| Citroën Berlingo-C3-C4-C4 Picasso-C5 II-Xsara Picasso 1.6 Hdi Motor DV6ATED4<br>Peugeot 206-207-307-407-Partner 1.6 Hdi Motor DV6TED4 –Incluye Bomba de Agua–   | <b>VKMC 03259</b>     | VKM 13140<br>VKM 23140                           | 137SP+254H           | VKPC 83259    |
| Citroën C5 II / C6 2.7 HDi / Peugeot 406 / 607 2.7 V6 HDi (Motor DT17TED4 D) / Land Rover<br>Discovery 2.7 TD (motor 276 DT)  | <b>VKMA 03261</b>     | VKM 13261<br>VKM 13262<br>VKM 23261<br>VKM 23261 | 195x29 / 85x20 (HSN) |               |
| Citroën C4-C4 Picasso-C5 II-C8 Motor 2.0 16V EW10A<br>Peugeot 307-407-807 Motor 2.0 16V EW10A   | <b>VKMA 03263 A</b>   | VKM 13263<br>VKM 23230                           | 153SP254H1           |               |
| Citroën Jumper I 2.5 D / Peugeot Boxer I 2.5 TD (motor DJ5T) / Peugeot 605 2.5 TD (motor DK5ATE)  | <b>VKMA 03300</b>     | VKM 13300<br>VKM 23300                           | 58141x28 HSN         |               |
| Citroën C5 I-II - C6 - Xantia II 3.0 Motor ES9A-ES9J4S-ES9J4- Peugeot 406-407-607-807<br>3.0 Renault Clio II - Laguna I-II Motor L7X721-722-760-762-700-701-731-733                                   | <b>VKMA 03902</b>     | VKM 23900<br>VKM 23901                           |                      |               |
| Daewo Matiz 1.0 desde 1999 hasta el 2003  | <b>VKMA 90008</b>     |  | 109x25HSN            |               |
| Daewo Matiz 1.0 desde 1999 hasta el 2003 –Incluye Bomba de Agua–  | <b>VKMC 90008</b>     | VKM 76102  | 109SHP+250H          | VKPC 90450    |
| Daewo Nubira I 1.4 - Nubira II 1.6 Motores F14D3/F16D3. –Incluye Bomba de de Agua–  | <b>VKMC 90402</b>     | VKM 70000<br>VKM 80000                           | 127SP254H            | VKPC 90402    |
| Daihatsu Applause-Charade-Feroza Motor 1.6 SOHC   | <b>VKMA 97501</b>     | VKM 77500  | 095SP254H            |               |
| Fiat Uno 705 1.5 motor 149 C1.000   | <b>VKMA 02111</b>     | VKM 12101  | 118SX190             |               |
| Fiat Duna-Fiorino-Uno-Palio-Siena 1.7 Diesel y Turbo Diesel   | <b>VKMA 02152 A</b>   | VKM 12151<br>VKM 22151                           | 168SHPN220           |               |
| Fiat Ducato (280-290) 1.9 D - Motor 149 B1.000  | <b>VKMA 02168</b>     | VKM 12153<br>VKM 22153                           | 170SHP254            |               |
| Fiat Ducato (280-290) 1.9 D - Motor 280 A1.000  | <b>VKMA 02169</b>     | VKM 12153<br>VKM 22153                           | 173SHP254            |               |
| Alfa Romeo 145-146-147-156 1.9 JTD<br>Fiat Brava-Bravo-Marea 1.9 JTD  | <b>VKMA 02179</b>     | VKM 12174<br>VKM 22179                           | 190SHPN240H          |               |
| Alfa Romeo 145-146-147-156 1.9 JTD<br>Fiat Brava-Bravo-Marea 1.9 JTD –Incluye Bomba de Agua–  | <b>VKMC 02179</b>     | VKM 12174<br>VKM 22179                           | 190SHPN240H          | VKPC 82665    |
| Fiat Brava-Bravo-Palio-Siena 1.3 16V - Motor Fire 1242 cc 16V   | <b>VKMA 02204 A</b>   | VKM 12201  | 124P8SD220H          |               |
| Fiat Brava-Bravo-Palio-Siena 1.3 16V - Motor Fire 1242 cc 16V –Incluye Bomba de Agua–<br>(Polea 23 dientes - Rotor 62,5 mm)   | <b>VKMC 02204-2</b>   | VKM 12201  | 124P8SD220H          | VKPC 82249 A  |
| Fiat Palio-Siena-Uno 1.3 8V (Motor Fire 1242 cc 8V) - Fiat Idea-Palio-Punto-Siena 1.4 8V (Motor Fire)   | <b>VKMA 02206 A</b>   | VKM 12299 H                                      | 129P8SD220H          |               |
| Fiat Fiorino, Idea, Palio II/III, Uno, Punto Todos motor 1,4 8v FIRE 310A2011   | <b>VKMA 02206/1 A</b> | VKM 12206 A                                      | 5627XS               |               |
| FIAT Brava-Bravo-Marea-Palio-Siena 1.6 16V  | <b>VKMA 02242 A</b>   | VKM 12242<br>VKM 22242 A                         | 158SHPN254H          |               |
| Alfa 147-155-156-166-GTVSpider 2.0 Motor AR32301-67204-32310-32303-32301  | <b>VKMA 02277</b>     | VKM 12173<br>VKM 12277<br>VKM 22177              | 168SHPN240H          |               |
| Iveco Daily II 2.5D motor 8140.67,8140.67F, 2.8 Tdi 8140.43R  | <b>VKMA 02383</b>     | VKM 22380<br>VKM 22385                           | 152SHDS300H          |               |
| Fiat Ducato   | <b>VKMA 02386</b>     | VKM 22385<br>VKM 22385                           | 154SHDS300H          |               |
| Fiat Ducato II 2.3 D Multijet / Iveco Daily III 2.3 JTD ( motor F1AE0481)   | <b>VKMA 02390</b>     | VKM 12206 A                                      | 5627XS               |               |
| Fiat Duna-Fiorino-Palio-Siena-Spazio-Uno 1.4-1.6 Nafta (Todos Motor Tipo)   | <b>VKMA 02410 A</b>   | VKM 12200 H                                      | 138SHPN150           |               |
| Fiat Palio-Uno Motor 1.3 MPI  | <b>VKMA 02412 A</b>   | VKM 12200 H                                      | 134SHPN170H          |               |
| Alfa Romeo 147-156-166-GT-GTV-Spider 2.5-3.0-3.2 V6 24V Motor 932/936.A000 - AR<br>32401/5 - 34201 - 36201 - 34301 - 36301 - 16101/2/5  | <b>VKMA 02540</b>     | VKM 12541<br>VKM 22540<br>VKM 22540              | 5476XS               |               |

| Aplicacion Vehículo (Resumen)  | Codigo Kit SKF | Tensor                                       | Correa                     | Bomba de Agua |
|--|----------------|--|----------------------------|---------------|
| Fiat Duna-Fiorino-Uno-Spazio 1.3 Diesel  | VKMA 02630 A   | VKM 12630 H<br>VKM 22630 H                   | 133SR220                   |               |
| Fiat Ducato (230) 2.8 TDI (Motor 8140.43) del 11/00 al 04/02   | VKMA 02986     | VKM 22385<br>VKM 22385<br>Accesorios         | 154SHDS300H                |               |
| Fiat Idea-Palio-Punto-Siena 1.8 8Vxt. Tensor 60 mm.)   | VKMA 05010 A   | VKM 15216                                    | 111SP170H                  |               |
| Fiat Idea-Palio-Punto-Siena 1.8 8Vxt. Tensor 59 mm.)   | VKMA 05012 A   | VKM 15402                                    | 111SP170H                  |               |
| Ford Escort-Galaxy-Orion 1.6-1.8-2.0 Nafta   | VKMA 01000 A   | VKM 11000 H                                  | 121SX180                   |               |
| Ford Escort-Galaxy-Orion 1.6-1.8-2.0 Nafta   | VKMA 01000 AD  | VKM 11000 H                                  | 121SX180H                  |               |
| Ford EcoSport-Nuevo Fiesta 1.4 TDCi  | VKMA 03140 A   | VKM 13140<br>VKM 23140                       | 144SP+254H                 |               |
| Ford Courier / Escort / Fiesta / Mondeo 1.8 Diesel y Turbo Diesel desde 11/1995 hasta 01/1997 Motores D18 y D18T   | VKMA 04106 A   | VKM 14103<br>VKM 14105<br>VKM 24100 H        | 116SHDN220H<br>085SHDN220H |               |
| Ford Courier / Escort / Fiesta / Mondeo 1.8 Diesel y Turbo Diesel desde 10/97 hasta 11/07 Motores D18 y D18T // Focus TD 90 CV   | VKMA 04107 A   | VKM 14103<br>VKM 14107<br>VKM 24107 H        | 116SHDN220H<br>085SHDN220H |               |
| Ford Escort-Mondeo 1.8 Diesel y Turbo Diesel 10/96 -> Motores RFN ,RFD ,RFA, RFK - 1753 cc -Incluye Bomba de Agua-   | VKMC 04107-1   | VKM 14103<br>VKM 14107<br>VKM 24107 H        | 116SHDN220H<br>085SHDN220H | VKPC 84620 A  |
| Ford Escort-Mondeo 1.8 Diesel y Turbo Diesel 10/96 -> Motores RFN ,RFD ,RFA, RFK - 1753 cc -Incluye Bomba de Agua-   | VKMC 04107-2   | VKM 14103<br>VKM 14107<br>VKM 24107 H        | 116SHDN220H<br>085SHDN220H | VKPC 84409 A  |
| Ford Escort-Mondeo 1.8 Diesel y Turbo Diesel 10/96 -> Motores RFN ,RFD ,RFA, RFK - 1753 cc -Incluye Bomba de Agua-   | VKMC 04107-3   | VKM 14103<br>VKM 14107<br>VKM 24107 H        | 116SHDN220H<br>085SHDN220H | VKPC 84408    |
| Ford Focus 1.8 TDCi Motor LD18 Lynx - 1753 cc  | VKMA 04108     | VKM 14108                                    | 091SP+200H                 |               |
| Ford Escort 1.6 16V - 1.8 16V Mondeo 2.0 16v - Nafta Motor Zetec   | VKMA 04212 A   | VKM 14210<br>VKM 24210 H<br>VKM 24211 H      | 131SP+254H                 |               |
| Ford Escort 1.6 16V - 1.8 16V - Mondeo 2.0 16v Nafta (Motor Zetec) -Incluye Bomba de Agua-   | VKMC 04212 A   | VKM 14210<br>VKM 24210 H<br>VKM 24211 H      | 131SP+254H                 | VKPC 84406 A  |
| Ford Focus 1.8 16V Motor ZH18 Zetec desde 10-98 hasta 01-99  | VKMA 04213     | VKM 14211<br>VKM 24212<br>VKM 24214          | 129SP+254H                 |               |
| Ford Focus 1.8 16V Motor ZH18 Zetec desde 01-99 hasta 11-04  | VKMA 04214     | VKM 14211<br>VKM 24213                       | 129SP+254H                 |               |
| Ford Puma Motor 1.7 16 V   | VKMA 04223     |  | 117SP+220H                 |               |
| Ford C-Max / Fiesta V (dde 04/05 hta 07/09) 1.6 16V / Fiesta VI 1.4 y 1.6 16V (dde 10/08 hta 07/09) / Focus C-Max 1.6 16V (dde 04/05 hta 03/07) / Focus II 1.6 16V (dde 04/05 hta 07/09) / Fusion 1.4 y 1.6 16 V (dde 04/05 hta 07/09) | VKMA 04224     | VKM 14224                                    | 76117x22 HSN               |               |
| Ford Transit 2.5 TD Motores 4EA  | VKMA 04301     | VKM 14301                                    | 45120x1                    |               |
| Ford Transit 2.5 TD Motores 4EB, 4EC   | VKMA 04304     |  | 130SHDN254HT               |               |
| Ford Transit 2.5 TD Motores 4GA, 4GB   | VKMA 04305     |  | 130SHDN276HT               |               |
| Ford Transit 2.5D 8v hasta 09/97, c/TensAut  | VKMA 04314 A   | VKM 14301                                    | 5571XS                     |               |
| Ford Transit 2.5D / TD 8v desde 09/97c/TensAut   | VKMA 04315 A   | VKM 14301                                    | 5572XS                     |               |
| Ford Focus II 2.5 20V / Kuga 2.5 / Mondeo IV 2.5 16V / S-Max 2.5 20V (motor Duratec)   | VKMA 06040     | VKM 16040<br>VKM 26602                       | 76142 x 23 HSN             |               |
| Ford Ranger  | VKMA 07405 A   | VKM 17405 H<br>VKM 27405 H                   | 118SP+300H                 |               |
| Ford Ranger. Todos Motor Maxion 2.5/2.8 D - Incluye Engranaje de Cigüeñal  | VKMA 07405 AC  | VKM 17405 H<br>VKM 27405 H<br>Engranaje Cig. | 118SP+300H                 |               |
| GM Corsa II-Meriva 1.8 8V (Diam. Ext. Tensor 60 mm.)   | VKMA 05010 A   | VKM 15216                                    | 111SP170H                  |               |
| GM Corsa II-Meriva 1.8 8V (Diam. Ext. Tensor 59 mm.)   | VKMA 05012 A   | VKM 15402                                    | 111SP170H                  |               |
| GM Corsa 1.6 8V -Incluye Bomba de Agua-  | VKMC 05121 A   | VKM 15121                                    | 111SP170H                  | VKPC 85206 A  |
| GM Corsa 1.6 8V  | VKMA 05121 A   | VKM 15121                                    | 111SP170                   |               |
| GM Astra-Corsa-Tigra-Vectra 1.4 16V-1.6 16V-1.8 16V  | VKMA 05150 A   | VKM 15216<br>VKM 25150 H<br>VKM 25152 H      | 169STP8M200H               |               |
| GM Meriva 1.8 16V (Diam. Ext. Tensor 60 mm.) - Motor Z18XE desde 05/03 al 03/07 (Hasta Motor N° 20EB2049)  | VKMA 05154     | VKM 15216<br>VKM 25152 H<br>VKM 25312        | 162STP8M200H               |               |
| GM Meriva 1.8 16V (Diam. Ext. Tensor 60 mm.) - Motor Z18XE desde 05/03 al 03/07 (Desde Motor N° 20EB2050)  | VKMA 05156     | VKM 15216<br>VKM 25158<br>VKM _____          | 162STP8M200H               |               |
| GM Corsa 1.7 Diesel  | VKMA 05214 A   | VKM 15215<br>VKM 25210 H                     | 136SHX254H                 |               |

Fiat

Ford

GM

|   | Aplicacion Vehículo (Resumen)  | Codigo Kit SKF | Tensor   | Correa                   | Bomba de Agua |
|---|--|----------------|--|--------------------------|---------------|
| GM  | GM Astra-Omega-Vectra 1.8 16V-2.0 16V  | VKMA 05222 A   | VKM 15202<br>VKM 25212 H<br>VKM 25212 H          | 169STP8M240H             |               |
|   | GM Astra 2.0 16V Motor X20EV   | VKMA 05224 A   | VKM 15202 A<br>VKM 25224<br>VKM 25224            | 168STP8M240H             |               |
|   | GM Vectra 2.2 16V Motor C22SEL   | VKMA 05228     | VKM 15230 A<br>VKM 25212<br>VKM 25212            | 171STP8M240H             |               |
|   | GM Astra - Cruze Motor 1,8 Motor 218XER / 2HO / F18D4  | VKMA 05260     | VKM 15260<br>VKM 25260                           | 5603XS                   |               |
|   | GM Astra-Kadett-Omega-Vectra 1.8-2.0   | VKMA 05402 A   | VKM 15402  | 146STP8M200H             |               |
|   | GM Astra-Corsa-Meriva 1.7 DTI Motor Y17DT (Imotor suzu)  | VKMA 05608     | VKM 15218<br>VKM 25208                           | 131SP+250HT              |               |
|   | GM S10. Todos Motor Maxion 2.5/2.8 D   | VKMA 07405 A   | VKM 17405 H<br>VKM 27405 H                       | 118SP+300H               |               |
|   | GM S10. Todos Motor Maxion 2.5/2.8 D - Incluye Engranaje de Cigüeñal   | VKMA 07405 AC  | VKM 17405 H<br>VKM 27405 H<br>Engranaje Cig.     | 118SP+300H               |               |
|   | GM Aveo 1,6 - Motor F16D3  | VKMA 90000     | VKM 7000<br>VKM 80000                            | 76127X2534HSN            |               |
|   | GM. Aveo 1.4 - 1.6. -Incluye Bomba de de Agua-   | VKMC 90402     | VKM 70000<br>VKM 80000                           | 127SP254H                | VKPC 90402    |
| Chevrolet Spark 1.0 desde el 2008 en adelante | VKMA 90008   | VKM 76102      | 109x25HSN  |                          |               |
| H   | Honda Civic II - III 1.6 Motor ZC DOHC - D16A7/9 DOHC hasta 1991   | VKMA 93002     | VKM 73000  |                          |               |
|   | Hyundai Elantra 1.8 / Lantra 1.8 (motor G4CN, DOHC) / Santamo 2.0 (motor G4CP, G4JP-G, DOHC) / Sonata 1.8 DOHC / 2.0 (motor G4CP, G4CP-D, G4CP-U DOHC) | VKMA 95005     | VKM 75044<br>VKM 75144<br>VKM 85000              | 77065x12.7 HSN           |               |
|   | Hyundai Galloper 2.5 TD Intercooler motor 4D56   | VKMA 95014     | VKM 75601<br>VKM 75612                           | 163SP254H<br>099SHP+190H |               |
|   | Hyundai H1-H100-Sonata 2.4   | VKMA 95015     | VKM 75008<br>VKM 75033                           | 055SHX127H<br>123SHX190H |               |
|   | Hyundai Coupe 2.7 G6BA-G - Santa Fe 2.7 6GEA - Sonota - Trajet 2.5-2.7 G6BV-6 - Magentis 2.5   | VKMA 95657     | VKM 75630<br>VKM 85148                           | 207RHP+320H              |               |
|   | Hyundai Elantra 2.0 CRDi-i30 2.0 CRDi-Santa Fe 2.0/2.2 CRDi-Sonata 2.0 CRDi -Tucson 2.0 CRDi   | VKMA 95660     | VKM 75628<br>VKM 85146                           | 123 x 28 H               |               |
| I   | Isuzu Trooper 2.8 TD Motor 4JB1T   | VKMA 99004     | VKM 79002<br>VKM 89003                           | 119SHX320                |               |
| K   | Kia Sportage 2.0 CRDi  | VKMA 95660     | VKM 75628<br>VKM 85146                           | 123 x 28 H               |               |
| Mercedes                                      | MB Sprinter. Todos Motor Maxion 2.5/2.8 D  | VKMA 07405 A   | VKM 17405 H<br>VKM 27405 H                       | 118SP+300H               |               |
|   | MB Sprinter. Todos Motor Maxion 2.5/2.8 D - Incluye Engranaje de Cigüeñal  | VKMA 07405 AC  | VKM 17405 H<br>VKM 27405 H<br>Engranaje Cig.     | 118SP+300H               |               |
|   | Kit para sist. Auxiliares MB Clase C (W202) - E (W210) Motor OM 611.960 CDI - ML (W163) - Motor OM 612.963 CDI   | VKMA 38020     | VKM 31041<br>VKM 38020                           | 6PK2270                  |               |
| Mazda / Mitsubishi                            | Mazda 323-626-929 Motor 2.0 DOHC   | VKMA 94000     | VKM 74000<br>VKM 84001<br>VKM 84002              | 192 x 30 H               |               |
|   | Mitsubishi Colt 1.8 (motor 4G67) / Eclipse 2.0 (motor 4G63) / Galant 2.0 (motor 4G63 DOHC) / Lancer 1.8 (motor 4G67).                                  | VKMA 95005     | VKM 75044<br>VKM 75144<br>VKM 85000              | 77065x12.7 HSN           |               |
|   | Mitsubishi L200-L300-Montero 2.5 TD Motor 4D56T  | VKMA 95014     | VKM 75601<br>VKM 75612                           | 163SP254H<br>099SHP+190H |               |
|   | Mitsubishi L200-L300-Montero-Pajero 2.4  | VKMA 95015     | VKM 75008<br>VKM 75033                           | 055SHX127H<br>123SHX190H |               |
|   | Mitsubishi L200 2.5 - Motor 4D56   | VKMA 95976     | VKM 75612<br>VKM 75676<br>VKM 85156<br>VKM 85156 | 92065x12,7 HSN           |               |
| Renault                                       | Renault Master Motor 2.5 D   | VKMA 02383     | VKM 22380<br>VKM 22385                           | 152SHDS300H              |               |
|   | Renault Master II 2.8 dTi  | VKMA 02386     | VKM 22385<br>VKM 22385                           | 154SHDS300H              |               |
|   | Renault Master II 2.8 dTi (Motor S9W700, S9W702) del 07/98 al 10/01 - (Incluye amortiguador/accesorios)  | VKMA 02986     | VKM 22385<br>VKM 22385<br>Accesorios             | 154SHDS300H              |               |
|   | Renault Clio 1.2-1.4   | VKMA 06000 A   | VKM 16000 H                                      | 095SP170H                |               |

| Aplicacion Vehículo (Resumen)  | Codigo Kit SKF | Tensor                                  | Correa      | Bomba de Agua |
|--|----------------|---|-------------|---------------|
| Renault Clio 1.2-1.4 –Incluye Bomba de Agua–   | VKMC 06000 A   | VKM 16000 H                             | 095SP170H   | VKPC 86409 A  |
| Renault Clio II 1.2 16 V Motor D4F –Incluye Bombas de Agua–  | VKMC 06002     | VKM 4617                                | 095SP+234H  | VKPC 86810    |
| Renault Clio II 1.2 16 V Motor D4F   | VKMA 06002 A   | VKM 4617                                | 095SP+234H  |               |
| Renault Clio–Kangoo 1.4 Motor K7J700, K7J 701  | VKMA 06003 A   | VKM 16001 H                             | 096SP170H   |               |
| Renault Clio–Kangoo 1.4 Motor K7J700, K7J 701 - 1390 cc / Clio II - Symbol 1.6 K7M 750 –Incluye Bomba de Agua–   | VKMC 06003 A   | VKM 16003                               | 096SP170H   | VKPC 86415 A  |
| Renault Clio–Twingo 1.2 Motor D7F  | VKMA 06010 A   | VKM 16000 H                             | 087SP170H   |               |
| Renault Clio–Twingo 1.2 Motor D7F –Incluye Bomba de Agua–  | VKMC 06010 A   | VKM 16000 H                             | 087SP170H   | VKPC 86215 A  |
| Renault Megane/Scenic 1.6 16V - Motor K4M  | VKMA 06020 A   | VKM 16020<br>VKM 4597                   | 132SP270H   |               |
| Renault Megane/Scenic/Logan/Sandero 1.6 16V - Motor K4M –Incluye Bomba de Agua y tapones arbol de levas–   | VKMC 06020 A   | VKM 16020 A<br>VKM 4597                 | 132SP270H   | VKPC 86416 A  |
| Renault 19–Clio 1.8 Nafta Motor F2N–F3P  | VKMA 06101 A   | VKM 16101 H<br>VKM 26101 H              | 125SP190H   |               |
| Renault Clio 2.0 16 Val. Sport motor F4R 830 desde 02/06 hasta 12/07 /Laguna II y III 2.0 16 Val. Motor F4R 764, 765, 784, 786, 787, 811, 886, 887 Megane / Scenic II 2.0 16 Val. motor F4R 770, 771, 774, 776 Desde 11/02 hasta 07/05 Incluye tapones de árbol de levas (2)                                   | VKMA 06106     | VKM 16550<br>VKM 4599                   | 126SP270H   |               |
| Renault Megane 2.0 16V Motor F4R - 1998 cc Desde mod. 2002 –Incluye Bomba de Agua–   | VKMC 06106     | VKM 16550<br>VKM 4599                   | 126SP270H   | VKPC 85304    |
| Renault Clio 2.0 16 Val. Sport motor F4R 730/732/736 desde 02/00 hasta 04/01 / Laguna I 2.0 16 Val. Motor F4R 780 desde 09/99 hasta 03/01 / Megane / Scenic 1.8 16 Val. F4P 720/722 desde 01/01 hasta 04/01 // 2.0 16 Val. motor F4R 740/741/747 Desde 09–99 hasta 04–01 Incluye tapones de árbol de levas (2) | VKMA 06107     | VKM 16550<br>VKM 4597<br>VKM 4611       | 128SP270H   |               |
| Renault Clio II 2.0 16 Val. Sport motor F4R 730, 732, 736, 738 desde 04/01 hasta 09/07 // Megane 1.8 16 Val. Motor F4P 722 desde 04/01 hasta 08/03 / 2.0 16 Val. motor F4R 740, 741, 746, 747 desde 04–01 hasta 06–04 Incluye tapones de árbol de levas (2)  | VKMA 06108     | VKM 16550<br>VKM 4599<br>VKM 4611       | 128SP270H   |               |
| Renault 19 1.9 Diesel Motor F8Q desde 10/96 - Sin Engranaje  | VKMA 06114 A   | VKM 16101 H<br>VKM 26101 H              | 153SP254H   |               |
| Renault Kangoo–Laguna–Megane–Scenic Motor 1.9 dTi - F9Q 734, 738, 748 desde 03/97 hasta 02/01  | VKMA 06115     | VKM 16101 H<br>VKM 26115                | 153SP260H   |               |
| Renault Clio–Express 1.9 Diesel Motor F8Q desde 10/96  | VKMA 06116 A   | VKM 16101 H<br>VKM 26102 H              | 151SP254    |               |
| Renault Megane–Scenic 1.9 dTi Motores F9Q 731, 744   | VKMA 06117     | VKM 16551<br>VKM 26117<br>VKM 26128     | 153SP260H   |               |
| Renault Laguna–Megane–Scenic 2.0 motor F3R 768 - F3R 791   | VKMA 06123 A   | VKM 16101 H<br>VKM 26101 H<br>VKM 26123 | 127SP190H   |               |
| Renault 19 1.9 Diesel Motor F8Q desde 10/96 - Con Engranaje  | VKMA 06124 A   | VKM 16101 H<br>VKM 26101 H<br>VKM 26125 | 153SP254H   |               |
| Renault Clio II–Express–Kangoo 1.9 D motor F8Q 630–632–662   | VKMA 06126 A   | VKM 16101 H<br>VKM 26102 H<br>VKM 26125 | 151SP254    |               |
| Renault Megane–Scenic 1.9 dTi motor F9Q 736  | VKMA 06128     | VKM 16551<br>VKM 26128                  | 153SP260H   |               |
| Renault Laguna II 1,9dCi (F9Q 664, 674, 758,759) Megane II 1,9dCi (F9Q 800, 803, 804, 808, 816, 818) Scenic II 1,9dCi (F9Q 803, 804, 812, 816, 818) Suzuki Grand Vitara 1,9 DDiS (F9Q)   | VKMA 06129     | VKM 16129                               | 133SP260H   |               |
| Renault Clio II–Logan–Sandero 1.5 dCi Motor K9K - 1461 cc –Incluye Bomba de Agua–  | VKMC 06130     | VKM 16102                               | 123SP270H   | VKPC 86417    |
| Renault Clio II–Logan–Sandero 1.5 dCi motor K9K  | VKMA 06130 A   | VKM 16102                               | 123SP270H   |               |
| Renault Megane II 1.5 dCi Motor K9K - 1461 cc –Incluye Bomba de Agua–  | VKMC 06132     | VKM 16102                               | 123SP270H   | VKPC 86418    |
| Renault 18–21–Fuego–Master motor J5R 718 - Trafic 2.0  | VKMA 06201     | VKM 16200                               | 116SP190    |               |
| Renault 18–21–Fuego–Master motor J7T 7822.2 - Trafic 2.2   | VKMA 06203     | VKM 16200                               | 118SP190    |               |
| Renault Espace–Master 2.1 D  | VKMA 06213     | VKM 16212<br>VKM 26211                  | 148SP254H   |               |
| Renault Megane 1.6 motor K7M 702,703,790 desde 01/96 hasta 08/03 –Incluye Bomba de Agua–   | VKMC 06415     | VKM 16000 H                             | 095SP170H   | VKPC 86415 A  |
| Renault Laguna II 2.2 dCi motor G9T 600,605,702,703,706,707 desde 10/01 hasta 09/07, Master 2.2 Dci G9T 720, 722, 750 ; 2.5 Dci motor G9U 720, 724, 750 , 754  | VKMA 06503     | VKM 16503<br>VKM 26503                  | 089SP+250H  |               |
| Renault Laguna 2.0 16 V Motor N7Q  | VKMA 06602     | VKM 16602<br>VKM 26602                  | 119SP190H   |               |
| Kit para sist. Auxiliares Renault Megane II 2.0 16V - Megane 1.9 dCi   | VKMA 36072     | VKM 36072                               | 7PK1127     |               |
| Rover 200 1.4 16V motor 14K4F / Rover 200 1.6 16V motor 16K4F  | VKMA 07301     | VKM 17301                               | 145SHP+260H |               |
| Land Rover Freelander 2.5 V6 (Motor 25 K4F) / Rover 45 2.0 V6 (motor 20 K4F) / 75 2.0 V6 (motor 20 K4F) / 75 2.5 V6 ( motor 25 K4F, KV 6) / 800 2.5 V6 (motor 25 K4F)  | VKMA 07307     | VKM ??<br>VKM 27307                     |             |               |
| Rover 100–200 1.4 16V motor 14K4F  | VKMA 07310     | VKM 17310                               | 143SHP+230H |               |

|   | Aplicacion Vehículo (Resumen)  | Codigo Kit SKF                      | Tensor   | Correa         | Bomba de Agua |
|---|--|-------------------------------------|--|----------------|---------------|
| Rover   | Land Rover Discovery - Todos Motor Maxion 2.5/2.8 D  | VKMA 07405 A                        | VKM 17405 H<br>VKM 27405 H                       | 118SP+300H     |               |
|   | Land Rover Discovery - Todos Motor Maxion 2.5/2.8 D - Incluye Engranaje de Cigüeñal  | VKMA 07405 AC                       | VKM 17405 H<br>VKM 27405 H<br>Engranaje Cig.     | 118SP+300H     |               |
| Subaru  | Subaru Impreza-Legacy 1.6-1.8-2.2 Motores EJ16 - EJ18 - EJ22E  | VKMA 98000                          | VKM 78000<br>VKM 88000<br>VKM 88000<br>VKM 88001 | 211SHP+300H    |               |
|   | Subaru Impreza-Legacy 1.6-1.8-2.2 Motores EJ16 - 1597 cc - EJ18 - 1820 cc - EJ22E - 2200 cc-Incluye Bomba de Agua-   | VKMC 98000                          | VKM 78000<br>VKM 88000<br>VKM 88000<br>VKM 88001 | 211SHP+300H    | VKPC 99407    |
|   | Subaru Forester-Impreza-Legacy-Outback 2.0-2.5 SOHC  | VKMA 98109                          | VKM 78005<br>VKM 88000<br>VKM 88001<br>VKM 88004 | 223 x 27 H     |               |
|   | Subaru Impreza 2.0 SOHC Motor EJ20E  | VKMA 98110                          | VKM 78005<br>VKM 88000<br>VKM 88000<br>VKM 88001 | 211SHP+300H    |               |
|   | Subaru Impreza 2.0 DOHC Motor EJ20G  | VKMA 98112                          | VKM 78005<br>VKM 88000<br>VKM 88000<br>VKM 88001 | 281SHP+300H    |               |
| Toyota  | Toyota Avensis 1.6 / Carina 1.6 (motor 4A-FE) / Corolla 1.5 (motor 4A-FE, 5A-FE) / Sprinter 1.5 (motor 5A-FE)  | VKMA 91005                          | VKM 71007  | 39117x21.1 HSN |               |
|   | Toyota Hilux 3.0 D Motor 1KZ - TE  | VKMA 91022                          | VKM 71014  | 102SP250       |               |
|   | Toyota 4 Runner-Land Cruiser-Hilux 2.4 D-TD  | VKMA 91124                          | VKM 71002<br>VKM 81002                           | 129SP310H      |               |
|   | Toyota Avensis 2.0 TD (CDT 220).1CDF-TV -Toyota Corolla 2.0 D-4D (CDE120).1CD-FTV  | VKMA 91303                          | VKM 71303<br>VKM 81204                           | 178 x 25 H     |               |
|   | Toyota Hilux 2.5 D-3.0 D4D Hasta 2005  | VKMA 91711 A                        | VKM 71014  | 097SP250H      |               |
| Toyota Fortuner - Hilux 2.5 -3.0 - Motor D4D - 4WD - Land Cruiser 3.0 | VKMA 91920   | VKM 91711<br>VKM 71014<br>VKM 71809 | 097SP250H  |                |               |
| Volvo   | Volvo C30 1.6 / S40 1.6 (dde el N motor 115003 en adelante) / V50 1.6 (dde el N motor 115450 en adelante) motor B4164 S3   | VKMA 04224                          | VKM 14224  | 76117x22 HSN   |               |
|   | Volvo C30 2.4, C70 II 2.4 / S40 II 2.4 (motor B5244 S4) / C30 2.5 Turbo / C70 II Turbo / S40 II Turbo (motor B5254 T3, B5254 T7) / S60 2.4 Turbo (Motor B5244 T3, B5244 T5 dde el Num 3188688 en adelante) / S60 2.5 Turbo (motor B 5254 T2, B5254 T4 dde el Num 3188689 en adelante) / S80 I 2.0 Turbo (motor B 5204 T3, B5204 T4, B 5204 T5 dde el Num 3188689 en adelante) / S80 I 2.3 Turbo ( B 5234 T7 dde el Num 3188689 en adelante) / S80 I 2.5 Turbo (motor B5254 T2 dde el Num 3188689 en adelante) / V50 2.4 (motor B5244 S4, B5244 S5) / V50 2.5 Turbo (motor B 5254 T3, B5254 T7) / V70 II 2.0 Turbo (motor 5204 T5 dde el Num 3188689 en adelante) / V70 II Turbo (motor B5254 T2 dde el Num 3188688 en adelante | VKMA 06040                          | VKM 16040<br>VKM 26602                           | 76142 x 23 HSN |               |
|   | Volvo 850-C70-S70-S40I   | VKMA 06602                          | VKM 16602<br>VKM 26602                           | 119SP190H      |               |
|   | Volvo 960 2.9 - S90-V90 3.0  | VKMA 06610                          | VKM 16612<br>VKM 26612                           | 152HSN280      |               |



# Kit de Distribución

## Solución completa en un solo embalaje

SKF Argentina SA • [www.skf.com.ar](http://www.skf.com.ar)  
 División Automotriz • Teléfono 4340 3208 / 3226 / 3278 • Fax 4340 3205  
[division.automotriz@skf.com](mailto:division.automotriz@skf.com)

AAVF090400

